



TECH BULLETIN



071
4/95

Published regarding engineering changes and improvements

SUBJECT: Plunger Rod Changes - HP Pumps

To improve the production capabilities and maintain quality control, the plunger rod and stud for the 4HP pump models have changed effective with **January 1, 1995** production. The pump model numbers will change from HP to DX.

Item	Old Part No.	New Part No.
4HP35G1, 4HP40G1		5DX35G1, 5DX40G1
Plunger Rod	46525 46728
O-Ring, Plunger Retainer	17399 N/A
Keyhole Washer.....	45697 N/A
Ceramic Plunger	46524 46727
Gasket, Plunger Retainer	45891 N/A
Seal Washer	N/A 46730
Barrier Slinger	43900 46732
Plunger Retainer w/Stud.....	104360 48201

The current Ceramic Plunger and Plunger Retainer will remain available for servicing older pump models, however, ***if the Plunger Rod wears, it will automatically be replaced with all of the above items as a set.*** If only ***one Plunger Rod*** needs replacement, it is acceptable to use one new style and two old style.

CAT PUMPS
Technical Services Department

Rev. 11/99